



XIRIUM

DIGITAL WIRELESS PRO AUDIO SYSTEM

Firmware

Version history - Issues & solutions



Firmware v1.1 / released on June 12th, 2014

HMI events included (Changing of the WLAN channel, Factory setting reset, IP address changing, Signal split for broadcast mode)

Signal split for broadcast mode

Optimized performance concerning FLASH

Improved temperature calibration

Fixed bugs during firmware update

In case of a mute or out of range situation the analog front end is no longer turned off.
Thus no interference in the signal occurs.